

CARFAX

Report

US \$49.99

2017 Mercedes-Benz Sprinter 3500XD

29,980 mi | VIN: WDAPF4CC5H9747663

chassis and Cab | 3.0L V6 F DOHC 24V | Diesel | Rear wheel drive



NO ACCIDENTS REPORTED

✓

No Accidents or Damage Reported to CARFAX

 3 Service History Records

 At Least 1 Open Recall

 3 Previous Owners

 Personal Vehicle

 Last Owned in Florida

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 8/7/26 at 8:22:19 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	Recall Reported	No New Recalls Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem	✓ Guaranteed No Problem	✓ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem	✓ Guaranteed No Problem	✓ Guaranteed No Problem

https://www.carfax.com/vehiclehistory/ar20/L25jdRelsOXdjSSV9M1oBmpWID2JelvVXiIXI3WWW0NwL0TNHgR0xls26uy60ZP0xNYdnEkGZGrXT8Bm...

1/6



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
View Terms | View Certificate

 Ownership History The number of owners is estimated	 Owner 1	 Owner 2	 Owner 3
Year purchased	2019	2023	2026
Type of owner	Personal	Personal	Personal
Estimated length of ownership	3 yrs. 8 mo.	3 yrs. 1 mo.	3 months
Owned in the following states/provinces	Michigan	Michigan	Florida
Estimated miles driven per year	--	--	--
Last reported odometer reading	205	9,092	29,980

 Detailed History

 Owner 1 Purchased: 2019		Personal Vehicle	
Date	Mileage	Source	Comments
03/31/2018	7	Loeber Motors, Inc. Lincolnwood, IL 847-675-1000 loebermotors.com  4.5 / 5.0 198 Verified Reviews  154 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
07/24/2019		Michigan Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as personal vehicle
08/01/2019		Michigan Motor Vehicle Dept. Milford, MI	Loan or lien reported
08/01/2019	205	Michigan Motor Vehicle Dept. Milford, MI	Title issued or updated - Registration issued or renewed - First owner reported
06/22/2020		Michigan Motor Vehicle Dept. Milford, MI	Registration issued or renewed
12/19/2020		Mercedes-Benz USA LLC	Manufacturer Safety recall issued - NHTSA #20V663 - Recall #2020120007 - Status: Remedy Available Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall  Learn more about this recall
Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain Mercedes-Benz and Freightliner Sprinter vehicles from platform 907 (VS30) and 906 (NCV3), the hydraulic power steering return line hoses may detach at their connection points under certain operating conditions and may cause hydraulic fluid to leak resulting in the loss of power steering.If the hydraulic power steering hose detaches, the driver will still have manual steering functionality, but increased steering effort is needed, particularly at low speeds. Sudden loss of power steering as well as the loss of hydraulic steering liquid to the road surface may increase the risk of a crash.An authorized Mercedes-Benz or Freightliner Sprinter dealer will check the return line connections of the power steering system and if needed, install the respective replacement clamp.			

If the hydraulic power steering hose detaches, the driver will still have manual steering functionality, but increased steering effort is needed, particularly at low speeds. Sudden loss of power steering as well as the loss of hydraulic steering liquid to the road surface may increase the risk of a crash.

Remedy: An authorized Mercedes-Benz or Freightliner Sprinter dealer will check the return line connections of the power steering system and if needed, install the respective replacement clamp.

06/19/2021	Michigan Motor Vehicle Dept. Milford, MI	Registration issued or renewed
08/06/2021	Mercedes-Benz USA LLC	Manufacturer Safety recall issued - NHTSA #21V042 - Recall #2021070007 - Status: Remedy Available Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall  Learn more about this recall
Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain 5-ton Sprinter vehicles from platform 906 (NCV3) that were upfitted into campers or recreational vehicles ("RVs"), one or more of the rear-wheel speed sensors may experience an electrical failure, which potentially lead to a disablement of the ESP control unit functions. Other performance issues might also be detected. If ESP control unit functions are disabled, vehicle driving stability may be impacted under certain driving conditions, increasing the risk of a crash. An authorized Mercedes-Benz or Freightliner Sprinter dealer will replace the rear-wheel speed sensors against a variant with higher robustness against moisture intrusion. If ESP control unit functions are disabled, vehicle driving stability may be impacted under certain driving conditions, increasing the risk of a crash. Remedy: An authorized Mercedes-Benz or Freightliner Sprinter dealer will replace the rear-wheel speed sensors against a variant with higher robustness against moisture intrusion.		
02/16/2022	Mercedes-Benz USA LLC	Manufacturer recall issued - Recall #2021070025 - Status: Remedy Available Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall  Learn more about this recall
Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vans, has determined that on certain Sprinter vehicles from platform 906 (NCV3), the Engine Control Unit (ECU) software, Transmission Control Unit (TCU) software, and Dosing Control Unit (DCU) software does not correspond to current series production specifications. An authorized Mercedes-Benz Sprinter dealer will update the Engine Control Unit (ECU) software, Transmission Control Unit (TCU) software, and Dosing Control Unit (DCU) software.		
06/29/2022	Michigan Motor Vehicle Dept. Milford, MI	Registration issued or renewed

 Owner 2 Purchased: 2023		Personal Vehicle	
Date	Mileage	Source	Comments
03/30/2023		Michigan Motor Vehicle Dept.	Vehicle purchase reported
04/03/2023	2,140	Michigan Motor Vehicle Dept. Milford, MI	Title issued or updated - Registration issued or renewed - New owner reported
08/10/2023		Victory Lane Quick Oil Change Milford, MI 248-684-7978 victorylane.net  4.7 / 5.0 190 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed

CARFAX

Warranty Check™

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this **2017 MERCEDES-BENZ SPRINTER 3500XD (WDAPF4CC5H9747663)**.

Please confirm remaining factory warranty and extended warranty options with your dealer or vehicle manufacturer.

2017 MERCEDES-BENZ SPRINTER 3500XD

VIN:	WDAPF4CC5H9747663
Estimated start date of warranty:	07/24/2019
Last CARFAX reading reported on 05/06/2026:	29,980 miles
Today's date:	08/07/2026

Type of Coverage	Original Warranty	Estimated Remaining Coverage
Basic	36 months or 36,000 miles	Coverage Expired
Drivetrain	36 months or 36,000 miles	Coverage Expired
Emissions	60 months or 100,000 miles	Coverage Expired
Corrosion	60 months or 100,000 miles	Coverage Expired
Transferable	No data reported to CARFAX	
Roadside	36 months or 36,000 miles	Coverage Expired
Safety belt & inflatable restraint	No data reported to CARFAX	
Specific Components	No data reported to CARFAX	
Notes	Corrosion Perforation - All Panels coverage: 3/Unlimited. Diesel Engine coverage: 5/100,000. California Emissions Diesel Short Term coverage: 5/100,000. California Emissions Diesel Long Term coverage: 7/70,000.	

i

CARFAX Warranty Check provides an **estimate** of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the MERCEDES-BENZ website.



CARFAX Buyback Guarantee

CARFAX Buyback Coverage:
08/07/2026 - 08/07/2027

CARFAX Vehicle Description:
2017 MERCEDES-BENZ SPRINTER 3500XD

VIN:
WDAPF4CC5H9747663

Body Style:
chassis and Cab

Driveline:
Rear wheel drive

Engine:
3.0L V6 F DOHC 24V

You may qualify
if you find that any of these problems were reported by a U.S.
Department of Motor Vehicles and were not included in this report.



Severe Damage:

- Salvage/Junk
- Rebuilt/Reconstructed
- Dismantled
- Fire/Flood/Hail



Odometer Problems:

- Exceeds Mechanical Limits
- Not Actual Mileage



Lemon History:

- Manufacturer Buyback

Terms and Conditions Apply

[View Terms and Conditions for CARFAX Buyback Guarantee coverage](#)